

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

UNIT	UNIT TYPE:													
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS		COUNTY: Currituck		
Closed MSWLF	X	HHW		White goods		Incin		T&P		FIRM		PERMIT NO.: 27-01		
CDLF		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		FILE TYPE: COMPLIANCE		

Date of Audit: Jan. 27, 2009 Date of Last Audit: Feb.23, 2007

FACILITY NAME AND ADDRESS:

Currituck County Landfill PO Box 38 Currituck, NC 27929

GPS COORDINATES: N: 36.39124 E: 76.04152

FACILITY CONTACT NAME AND PHONE NUMBER:

Brenda McQueen (252) 232-2504

FACILITY CONTACT ADDRESS:

same

AUDIT PARTICIPANTS:

Chuck Boyette, Solid Waste Section

STATUS OF PERMIT:

Closed

PURPOSE OF AUDIT:

Comprehensive Audit

NOTICE OF VIOLATION(S):

None

You are hereby advised that, pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Statute or Regulations. For the violation(s) noted here, you may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

STATUS OF PAST NOTED VIOLATIONS:

 N/Δ

AREAS OF CONCERN AND COMMENTS:

- 1. Closure letter was reviewed with emphasis on post closure care.
- 2. The monitoring wells were locked, had tags and were protected. Samples were last pulled in December 2008.
- 3. There was no evidence of leachate breakout problems.
- 4. No on site erosion was observed.
- 5. Adequate ground cover was provided on all areas with the exception of a few small patches (+/- 10 square feet). Please make plans to reseed those areas in the Spring.

FACILITY COMPLIANCE AUDIT REPORT

Division of Waste Management Solid Waste Section

Page 2 of 2

- 6. No surface water was impounded on the closed landfill unit.
- 7. No settling of the cap material was noted over the landfill unit.
- 8. The site can be secured by gates and cables when the scale attendant for the transfer facility is not on site.
- 9. Some of the vegetative cover was about 2 foot high, therefore plans for mowing the cap should be underway.

Please contact me if you have any questions or concerns regarding this audit report.											
Chuck Boyette (name) Environmental Senior Specialist Regional Representative		Phone: <u>(252)</u>	794-2								
Delivered on: Feb.6, 2009 by	x	Hand delivery		US Mail		Certified No. []					

cc: Mark Poindexter, Field Operations Branch Supervisor Dennis Shackelford, Eastern District Supervisor Donald Herndon, Compliance Officer Wendy McNeil, Eastern Admin Support If NOV - County Solid Waste Director